

1. Truck scales No 1
2. Warehouses
3. Warehouses
4. Truck scales No 2
5. Trolley unloading area
6. Utility facilities
7. Grain intake area
8. Biomass intake area
9. Cationic starch unloading area
10. Elevator
11. Mill
12. Chemicals terminal
13. Warehouse
14. Biomass boiler plant
15. Cationic starch shop
16. Elevator
17. Products storage/packaging area
18. Starch shop
19. Boiler plant
20. Feed shop
21. Glucose syrup shop
22. Engineer workshop
23. Biomass storage facilities
24. Feed, big bags
25. Feed, containerless
26. Gluten, starch, containerless



- 5. Grain unloading No. 2
- 7. Grain unloading No. 1
- 8. Biomass unloading
- 9. Cationic starch, containerless, S7
- 12. Chemicals
- 13. Cationic starch, big bags
- 17. Gluten, starch
- 18. C-syrup, K4/K5
- 21. Glucose syrup, GS1/GS2
- 24. Feed, big bags
- 25. Feed, containerless, F12
- 26. Gluten, starch, containerless, S6
- K3 – GFL (Glucose production waste)



Meeting place

- ← Grain
- ← Glucose syrup
- ← Starch, gluten
- ← Cationic starch
- ← Biomass
- "Roquette Amilina" AB territory boundary



EMERGENCY NUMBER +370 650 20195



There is a 20 km/h speed limit within the company's territory.



Photography and video are prohibited within the company's territory without a permit.



Smoking is prohibited except in designated areas. Violations are recorded and fines are imposed after the warning.



Driving while using a mobile phone is prohibited.



Follow the instructions given by company employees.
If there are no signs present, please follow all traffic law requirements.



Only walk on paths designated for pedestrians.



Buckle your seat belt when driving.



Be careful! Forklifts can use various routes.



Before crossing the railroad crossing, stop to make sure no locomotives are approaching.



Only park your vehicles in places marked with parking signs.
Parking vehicles on pedestrian paths is prohibited.



Upon parking a truck in a loading/unloading zone, turn off the engine, engage the manual brake, and secure the wheels of the truck with chocks.



Standing and observing the loading/unloading process can only be done from a location indicated by our employees. Being in the vehicle's trailer during loading is prohibited.



When opening/closing/sealing manholes of a truck cistern or when carrying out other work at a high above 1.2 m from the ground surface, the driver must:

- Use movable guards and secure them properly;
- Wear a securely fastened protection helmet;
- In places where anchor lines are installed, use safety harnesses and fasten them to an anti-fall device.



Wearing safety shoes and a signal vest is mandatory when within our territory.
When at a loading/unloading zone, wearing all of the personal safety items indicated by the signs is mandatory.



Vehicles must be in proper technical working order.



You must immediately notify the company's employees or contact security employees in the event of spilled oil, chemicals or other dangerous substances.



Any pollution or littering is prohibited, and fines will be issued after an initial warning.



It is prohibited to bring unauthorized persons/passengers to the territory of the Company.

IF THESE RULES ARE NOT FOLLOWED, LOADING WORK WILL NOT BE PERFORMED!